FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

 Client ID:
 M05820
 Client:
 Alaskan Copper Works

 Date Received:
 07/22/10
 Project:
 PO M05820, F&BI 007246

 Date Received:
 07/22/10
 Po M05820, F&BI 007246

 Date Extracted:
 07/23/10
 Lab ID:
 007246-01 x10

 Date Analyzed:
 07/29/10
 Data File:
 007246-01 x10.014

Matrix: Water Instrument: ICPMS1 Units: ug/L (ppb) Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 89 60 125

Concentration

Analyte: ug/L (ppb)

 Chromium
 773

 Nickel
 660

 Copper
 564

 Zinc
 37.5

FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 07/23/10
Date Analyzed: 07/29/10
Matrix: Water
Units: ug/L (ppb)

Zinc

Client: Alaskan Copper Works
Project: PO M05820. F&BI 007246
Lab ID: I0-393 mb

Data File: I0-393 mb .008
Instrument: ICPMS1
Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 100 60 125

<1

Concentration ug/L (ppb)

Chromium <1
Nickel <1
Copper <1

FRJEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Date of Report: 08/03/10 Date Received: 07/22/10

Project: Metro Self Monitor, PO M05820, F&BI 007246

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 007222-01 (Matrix Spike)

				Percent	Percent		
	Reporting	Spike	Sample	Recovery	Recovery	Acceptance	RPD
Analyte	Units	Level	Result	MS	MSD	Criteria	(Limit 20)
Chromium	ug/L (ppb)	20	<1	100	98	67-132	2
Nickel	ug/L (ppb)	20	1.87	93	91	73-119	2
Copper	ug/L (ppb)	20	<1	97	94	50-144	3
Zinc	ug/L (ppb)	50	3.94	97	97	46-148	0

Laboratory Code: Laboratory Control Sample

			Percent	
	Reporting	Spike	Recovery	Acceptance
Analyte	Units	Level	LCS	Criteria
Chromium	ug/L (ppb)	20	105	66-135
Nickel	ug/L (ppb)	20	107	67-134
Copper	ug/L (ppb)	20	112	66-134
Zinc	ug/L (ppb)	50	105	57-135

FRJEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- $\mbox{d} s$ The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- $\mbox{d} v$ Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- $\,$ nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- ${\bf x}$ The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

nn7246		ĸ	SA	MPLE CH	AIN OF C	UST	OD	Y	1E	7	2/2	2	//	0	A		4
1			MPLE CHAIN OF CUSTODY ME 7/22/10 AI 4 SAMPLEBS (signature) Page # of														
Send Report To Creacus Monpson							\Rightarrow	_	PO	ш	_					D TIME	
Company ALASKAN COOPER Works			Meta	NAMEZNO.	Mo	volen	,					Ø	RUS	Hard (2)	<u>oey</u>		
Address 628 S. Honor 2 &			PROJECT NAME/NO. Medro Seld mondar MOS820 CRUSH Control Rush charges authorized by:								ized by:						
Address 4 San			REMARKS SAMPLE DISPOSAL														
City, State, ZIP			Dispose after 30 days ☐ Return samples														
Send Report To See Son Thompson Company A (AEKAN Copper Works Address 628 S. Hondow & City, State, ZIP Seattle with 7842 Phone # 206-382-4309																ructions	
u. T		G.		ANALYSES REQUESTED													
							. je	11B	5		3						
			43		ء بير	TPH-Diesel	idog	802	y 82	70	¥.						
Sample ID	Lab ID	Date	Time	Sample Typ	e # of containers	Q.	Ö.	by by	d ec	HFS	- 1						Notes
						Idi	TPH-Casoline	BTEX by 8021B VOCs by 8260	SVOCs by 8270		3						
								m /	S		(g)	_		41	_ _		
m05820	01	Fresho	2:200	Hre	1				¥.								
	0.9																
	1						+	+									
							-	+-			-				-		
							\perp										
												1					
							+					1			_		
							-	+				-					
	}																
												14					
							+					-				-	
		-					+	+		\vdash		4			_		
	1 1		No. of West of State						20-42-27-0								
Friedman & Bruya, Inc.		SIGNATUI	RE		PRINT	NAM	E				CON	/PA	NY		DA		TIME
3012 16th Avenue West	Religious duy.			Geron Thomas A				JC2	W Thelio 3.200								
Seattle, WA 98119-2029	Received by:			Fuellower E			d										
Ph. (206) 285-8282	Relinguished by:			1	1	[<i>]</i> /	<u> </u>			10	- (<u> </u>			1/2	<i>J</i> .	7/
Fax (206) 283-5044	Received by:	7-1-1-	*****		/	_			+								
ORMS\COC\COC.DOC				1			Ç.	mnle	9 70	coivi	id at	7	5	°C			i

FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

August 3, 2010

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on July 22, 2010 from the Metro Self Monitor, PO M05820, F&BI 007246 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0803R.DOC